

Stepper Motor Driver PCB Layers

Kyle Noble

January 2020




Figure 1: All layers




Figure 2: All layers, no copper pour




Figure 3: Top layer and silkscreen




Figure 4: Top layer and silkscreen, no copper pour




Figure 5: Bottom layer and silkscreen




Figure 6: Bottom layer and silkscreen, no copper pour